



Radon Test Report

September 20, 2018
Batch #: 092018-1

Customer:

Adam Smith
555 Bismuth Blvd.
Frederick MD 21704

Test Site:

Adam Smith
555 Bismuth Blvd.
Frederick MD 21704

E-PERM® Electret Ion Chambers were used for short-term radon screening measurements that were conducted at the above referenced test site by: ABC Radon Testing Company

The Results are as follows:

Serial No.	Type	Location	Test Start Date		Test End Date		Test Results
SAA001	SST	Basement	21-Sep-2018	10:31 AM	23-Sep-2018	10:49 AM	4.4
SAA002	SST	Basement	21-Sep-2018	10:31 AM	23-Sep-2018	10:49 AM	4.1

Average Radon Concentration in: Basement 4.3 pCi/L

Deployed By: Joe Tech 1234567890
Retrieved By: Joe Tech 1234567890
Analyzed By: Joe Tech 1234567890 **Reader S/N:** E001 **Reader Calibration Due:** 20-Sep-2019

Radon Health Risk Information

Radon is the second leading cause of lung cancer after smoking. The U.S. Environmental Protection Agency (EPA) and the Surgeon General strongly recommend that further action be taken when a home's radon test results are 4.0 pCi/L or greater. The national average indoor radon level is about 1.3 pCi/L. The higher the home's radon level, the greater the health risk to you and your family. Reducing your radon levels can be done easily, effectively and fairly inexpensively. Even homes with very high radon levels can be reduced below 4.0 pCi/L. Please refer to the EPA website at www.epa.gov/radon for further information to assist you in evaluating your test results or deciding if further action is needed.

Signature: Joe Tech

Date: 20-Sep-2018



Radon Test Report

September 20, 2018
 Batch #: 092018-1


Customer:

Adam Smith
 555 Bismuth Blvd.
 Frederick MD 21704

Test Site:

Adam Smith
 555 Bismuth Blvd.
 Frederick MD 21704

Graphical Report for Tamper Monitor #351





Radon Test Report

September 20, 2018

Batch #: 092018-1

Customer:

Adam Smith
555 Bismuth Blvd.
Frederick MD 21704

Test Site:

Adam Smith
555 Bismuth Blvd.
Frederick MD 21704

Hourly Detailed Report for Tamper Monitor #351

Record #	Date/Time	Fahrenheit (°F)	Pressure (inHg)	Humidity (%)	Tilts
1	20-Sep-2018 10:31	63	29.8	42	0
2	20-Sep-2018 11:31	69	29.7	37	0
3	20-Sep-2018 12:31	74	29.7	33	0
4	20-Sep-2018 13:31	74	29.7	31	0
5	20-Sep-2018 14:31	74	29.7	30	0
6	20-Sep-2018 15:31	74	29.7	30	0
7	20-Sep-2018 16:31	74	29.7	29	0
8	20-Sep-2018 17:31	73	29.7	29	0
9	20-Sep-2018 18:31	72	29.8	30	0
10	20-Sep-2018 19:31	71	29.8	31	0
11	20-Sep-2018 20:31	72	29.8	31	0
12	20-Sep-2018 21:31	74	29.8	30	0
13	20-Sep-2018 22:31	74	29.8	29	0
14	20-Sep-2018 23:31	75	29.8	29	0
15	21-Sep-2018 00:31	75	29.8	28	0
16	21-Sep-2018 01:31	76	29.7	27	0
17	21-Sep-2018 02:31	76	29.7	27	0
18	21-Sep-2018 03:31	75	29.7	27	0
19	21-Sep-2018 04:31	74	29.7	26	0
20	21-Sep-2018 05:31	73	29.7	27	0
21	21-Sep-2018 06:31	73	29.7	27	0
22	21-Sep-2018 07:31	73	29.7	27	0
23	21-Sep-2018 08:31	73	29.7	28	0
24	21-Sep-2018 09:31	73	29.7	28	0
25	21-Sep-2018 10:31	73	29.7	28	0
26	21-Sep-2018 11:31	72	29.6	28	0
27	21-Sep-2018 12:31	72	29.6	29	0
28	21-Sep-2018 13:31	71	29.6	29	0
29	21-Sep-2018 14:31	71	29.6	29	0
30	21-Sep-2018 15:31	71	29.6	29	0
31	21-Sep-2018 16:31	71	29.6	30	0
32	21-Sep-2018 17:31	71	29.6	30	0
33	21-Sep-2018 18:31	73	29.6	30	0
34	21-Sep-2018 19:31	73	29.6	30	0
35	21-Sep-2018 20:31	72	29.0	38	9
36	21-Sep-2018 21:31	72	28.9	38	8
37	21-Sep-2018 22:31	72	28.9	39	0
38	21-Sep-2018 23:31	72	28.9	39	0
39	22-Sep-2018 00:31	72	28.9	39	0
40	22-Sep-2018 01:31	72	28.9	40	0
41	22-Sep-2018 02:31	72	29.0	40	0
42	22-Sep-2018 03:31	72	29.0	40	0



Radon Test Report

September 20, 2018

Batch #: 092018-1

Customer:

Adam Smith
555 Bismuth Blvd.
Frederick MD 21704

Test Site:

Adam Smith
555 Bismuth Blvd.
Frederick MD 21704

Record #	Date/Time	Fahrenheit (°F)	Pressure (inHg)	Humidity (%)	Tilts
43	22-Sep-2018 04:31	72	28.9	40	0
44	22-Sep-2018 05:31	72	28.9	39	0
45	22-Sep-2018 06:31	72	29.0	39	0
46	22-Sep-2018 07:31	72	29.0	39	0
47	22-Sep-2018 08:31	72	29.0	38	0
48	22-Sep-2018 09:31	72	29.0	38	0
49	22-Sep-2018 10:31	72	29.1	37	0
50	22-Sep-2018 11:31	72	29.1	37	0
51	22-Sep-2018 12:31	72	29.1	35	0
52	22-Sep-2018 13:31	71	29.1	33	0
53	22-Sep-2018 14:31	70	29.1	32	0
54	22-Sep-2018 15:31	69	29.2	32	0
55	22-Sep-2018 16:31	68	29.2	31	0
56	22-Sep-2018 17:31	68	29.2	31	0
57	22-Sep-2018 18:31	68	29.2	31	0
58	22-Sep-2018 19:31	68	29.3	31	0
59	22-Sep-2018 20:31	68	29.3	31	0
60	22-Sep-2018 21:31	69	29.3	31	0
61	22-Sep-2018 22:31	68	29.3	31	0
62	22-Sep-2018 23:31	68	29.3	31	0
63	23-Sep-2018 00:31	68	29.4	30	0
64	23-Sep-2018 01:31	68	29.4	30	0
65	23-Sep-2018 02:31	68	29.4	30	0
66	23-Sep-2018 03:31	68	29.5	30	0
67	23-Sep-2018 04:31	68	29.5	30	0
68	23-Sep-2018 05:31	69	29.5	29	0
69	23-Sep-2018 06:31	69	29.5	29	0
70	23-Sep-2018 07:31	69	29.6	29	0
71	23-Sep-2018 08:31	69	29.6	28	0
72	23-Sep-2018 09:31	69	29.6	28	0
73	23-Sep-2018 10:31	69	29.6	28	0
74	23-Sep-2018 11:31	69	29.7	27	0
75	23-Sep-2018 12:31	69	29.7	27	0
76	23-Sep-2018 13:31	69	29.7	26	0
77	23-Sep-2018 14:31	67	29.7	24	0
78	23-Sep-2018 15:31	67	29.7	23	0
79	23-Sep-2018 16:31	68	29.7	23	0